



# SWITCHES


## TOGGLE 30 & 60 amp




**80898 3PDT**  
ON - OFF - ON  
30 amp. 125 volt  
20 amp 250 volt




**80899 4PDT**  
ON - OFF - ON  
30 amp. 125 volt  
20 amp 250 volt




**80988 EAR DPDT**  
ON - OFF - ON  
30 amp. 125 volt  
20 amp. 250 volt




**7576K2 SPST**  
ON - OFF  
30 amp. 125 volt  
25 amp. 250 volt




**MC360 L 3PST**  
ON - OFF  
3 PHASE  
60 amp. 600 volt




**7810 U 3PST 3 ph**  
30 amp. 600 volt  
**6810 U DPST 1 ph**  
30A 250 20A 600  
ON - OFF




**80404 3PST**  
ON - OFF  
3 PHASE  
30 amp. 250 volt  
20 amp 600 volt




**3032-SW DPST**  
ON - OFF  
30 amp.  
125 - 277 VAC




**100006 ZA DPST**  
ON - OFF  
30 amp.  
250 volt



**100006 DPST**  
ON - OFF  
30 amp.  
250 volt



**6808 U DPST**  
ON - OFF  
30 amp. 250 volt  
20 amp. 600 volt



**8684 U SPST**  
ON - OFF  
30 amp.  
250 volt

**MORE SWITCHES?  
VISIT OUR WEBSITE**

**Eurton**

Motor rewinding & parts

9920 Painter Ave.  
Santa Fe Springs, CA 90670

**800-423-4789**  
**fax 562-946-0014**  
[www.eurtonelectric.com](http://www.eurtonelectric.com)