




p4099[2] (4000.00 μs)



Reference quantities
p2000... r2004



<1> The input signals are referred to the reference quantities p2004 ... r2004 (100 % ≙ p200x).

1	2	3	4	5	6	7	8
DO: TB30					fp_9106_51_eng.vsd	Function diagram	
Terminal Board 30 (TB30) - Analog outputs (AO 0 ... AO 1)					25.10.05 V02.05.00	SINAMICS	
							- 9106 -