

**type BA-200 refill power fuses • time lag refills**

2.4 to 34.5 kv

Curves are based on tests starting with fuse units at an ambient temperature of 25°C and without initial load. Curves are plotted to maximum test points so all variations should be negative.

curve no. **4**

reference no. 280211

January, 1961

Westinghouse Electric Corporation

Assembled Switchgear and Devices Dept.: East Pittsburgh Division • East Pittsburgh, Pa.

printed in U.S.A.